


CR NUMBER 24-2946	ACCIDENT DATE 2-27-24	ACCIDENT TIME 1000	DAY OF WEEK TUE	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 1800 RHODES RD (COLLEGE TOWERS)			WEATHER CLOUDY / RAIN	
VEHICLE NO. 1 PICTURES TAKEN		VEHICLE NO. 2 (OR PROPERTY DAMAGED)		
DRIVER LAST FIRST MIDDLE DOB COLE TIMOTHY 12-13-72	DRIVER LAST FIRST MIDDLE DOB			
ADDRESS 301 S DEPEYSTER ST	ADDRESS			
CITY, STATE, ZIP PHONE NUMBER KENT OH 44240	CITY, STATE, ZIP PHONE NUMBER			
DRIVER'S LICENSE NUMBER STATE OH	DRIVER'S LICENSE NUMBER STATE			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE CITY OF KENT	VEHICLE OWNER'S NAME LAST FIRST MIDDLE			
ADDRESS 930 OVERHOLT RD	ADDRESS			
CITY, STATE, ZIP PHONE NUMBER KENT OH 44240	CITY, STATE, ZIP PHONE NUMBER			
VEHICLE YEAR MAKE MODEL COLOR 2023 CHEVY TAHOE BLACK	VEHICLE YEAR MAKE MODEL COLOR			
LICENSE PLATE NUMBER STATE 2 VIN 1GNSKLED9PR198624	LICENSE PLATE NUMBER STATE			
INSURANCE COMPANY LOVE POL.# 023PKG8087-02	INSURANCE COMPANY			
PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input checked="" type="checkbox"/> REAR <input checked="" type="checkbox"/> LEFT <input type="checkbox"/> RIGHT BUMPER AND TAILLIGHT	PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT			
DESCRIBE HOW ACCIDENT OCCURRED VEH 1, A MARKED POLICE SUV, BACKED TO THE EAST FROM THE NORTH INTO A PARKING STALL. VEH 1 STRUCK A YELLOW METAL POLE ON THE SE CORNER OF THE STALL WITH THE LR CORNER OF VEH 1. VEH 1 BUMPER AND LR TAIL LIGHT WAS DAMAGED. VEH 1'S PARKING ASSIST WAS DISABLED IN THE VEHICLE'S SETTINGS AND WAS NOT FUNCTIONAL AT THE TIME OF THE CRASH.				
SKETCH HOW ACCIDENT OCCURRED 				
OFFICER / SUPERVISOR SIGNATURE LT WHEELER				