


CR NUMBER 23-5129	ACCIDENT DATE 4/3/23	ACCIDENT TIME 16:11	DAY OF WEEK Monday	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 609 S Lincoln St Kent OH 44240			WEATHER Clear	

VEHICLE NO. 1					VEHICLE NO. 2 (OR PROPERTY DAMAGED)				
DRIVER LAST FIRST MIDDLE DOB Hutchings, Olivia, Grace 9/9/2003	DRIVER LAST FIRST MIDDLE DOB								
ADDRESS 609 S Lincoln St Apt C104	ADDRESS								
CITY, STATE, ZIP PHONE NUMBER Kent, OH 44240	CITY, STATE, ZIP PHONE NUMBER								
DRIVER'S LICENSE NUMBER STATE OH	DRIVER'S LICENSE NUMBER STATE								
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Hutchings, Tray	VEHICLE OWNER'S NAME LAST FIRST MIDDLE Cottrell, David, Mark								
ADDRESS 670 Quarry Ln NE	ADDRESS 668 Treeside dr								
CITY, STATE ZIP PHONE NUMBER Warren, OH 44483	CITY, STATE, ZIP PHONE NUMBER Stow, OH 44224								
VEHICLE YEAR MAKE MODEL COLOR 2019 Toyota RAV4 Gray	VEHICLE YEAR MAKE MODEL COLOR 2022 Toyota Corolla Silver								
LICENSE PLATE NUMBER STATE JWP1728 OH	LICENSE PLATE NUMBER STATE JTR9355 OH								
INSURANCE COMPANY Statefarm 2264999 SFP 35	INSURANCE COMPANY								
PARTS OF VEHICLE DAMAGED <input checked="" type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input checked="" type="checkbox"/> RIGHT Front Right Fender	PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input checked="" type="checkbox"/> REAR <input checked="" type="checkbox"/> LEFT <input type="checkbox"/> RIGHT Rear left Fender								

DESCRIBE HOW ACCIDENT OCCURRED

Vehicle 1 was attempting to pull into a parking space and struck vehicle 2 which was parked and unoccupied.

SKETCH HOW ACCIDENT OCCURRED



OFFICER /SUPERVISOR SIGNATURE

[Signature] 252 *[Signature]* 276