




CR NUMBER 23-201	ACCIDENT DATE 1-4-23	ACCIDENT TIME 2230	DAY OF WEEK WED	<input type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input checked="" type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 1678 Eastlan Ct Kent OH 44240			WEATHER	
VEHICLE NO. 1			VEHICLE NO. 2 (OR PROPERTY DAMAGED)	
DRIVER LAST FIRST MIDDLE DOB	DRIVER LAST FIRST MIDDLE DOB Kore, Shashi K. 2-19-99			
ADDRESS	ADDRESS 1678 Eastlan Ct #172			
CITY, STATE, ZIP PHONE NUMBER	CITY, STATE, ZIP PHONE NUMBER Kent OH 44240			
DRIVER'S LICENSE NUMBER STATE	DRIVER'S LICENSE NUMBER STATE OH			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE	VEHICLE OWNER'S NAME LAST FIRST MIDDLE Richard, Tyler W.			
ADDRESS	ADDRESS 1678 Eastlan Ct #274			
CITY, STATE, ZIP PHONE NUMBER	CITY, STATE, ZIP PHONE NUMBER Kent, OH 44240			
VEHICLE YEAR MAKE MODEL COLOR	VEHICLE YEAR MAKE MODEL COLOR 2022 Nissan Rogue White			
LICENSE PLATE NUMBER STATE	LICENSE PLATE NUMBER STATE JVC 7922 OH			
INSURANCE COMPANY	INSURANCE COMPANY Progressive 903522374			
PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input checked="" type="checkbox"/> LEFT <input type="checkbox"/> RIGHT 	PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input checked="" type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT 			
DESCRIBE HOW ACCIDENT OCCURRED On 1-4-22 unit #1 was parked in front of 1678 Eastlan Ct next to unit #2. Unit #2 backed out of the spot and struck unit #1.				
OFFICER/SUPERVISOR SIGNATURE Lt. Short #228			SKETCH HOW ACCIDENT OCCURRED 	
			INDIcate NORTH BY ARROW not to scale	